DOCUMENT No. IL4-TP17 20 MARCH 1973

# FINAL TEST REPORT ILLIAC IV COMPUTER SYSTEM ACCEPTANCE TEST

CONTRACT No. AF 30(602)-4144

BURROUGHS CORPORATION

Defense, Space and Special Systems Group

# CONTENTS

		Page
FORE	WORD	iii
1.0	OVERVIEW 1.1 General 1.2 Requirements 1.3 Results 1.4 Conclusions	1 1 1 1 4
2.0	SUMMARY OF SYSTEM MALFUNCTIONS	5
3.0	AVAILABILITY CALCULATION	14
4.0	MTBF AND MTTR FOR SYSTEMS COMPONENTS	15
5.0	SUMMARY OF B6700 MALFUNCTIONS	17
6.0	QUADRANT CLOCK FREQUENCY	19
7.0	ENVIRONMENTAL CONDITIONS	20
APPE	NDIX General Determination of Up, Down and Non-Productive Time System Event Log	23 24 75259- 75343

# TABLES

I	ILLIAC IV Availability Summary	3
II	Summary of System Malfunctions	6
III	Causes of Failures	12
IV	MTBF and MTTR for Systems Components	16
V	List of Malfunctions and Resulting Non-Productive Time	18
VI	Product Assurance Daily Check List	22

# FOREWARD

The procedure and requirements for this acceptance test, along with a description of the equipment under test and the software used in the test are delineated in the Acceptance Test Procedure for ILLIAC IV Computer System dated 15 November 1972.

The purpose of this report is to present the results of that test with any variances from the original test plan and some general conclusion.

#### 1. OVERVIEW

#### 1.1 General

The Acceptance Test for the ILLIAC IV computer system was begun 0800 hours, 27 November 1972, and was terminated 1202 hours, 8 December 1972. The Acceptance Test procedure for the ILLIAC IV computer system, Burroughs Document No. IL4-TP14/15 Rev. A, dated 15 November 1972, was used as a basis for conducting the test.

#### 1.2 Requirements

The test procedure required:

- (1) that the array subsystem shall have a minimum clock rate of 15.0 MHz, and
- (2) that the system (excluding the B6700) shall demonstrate an availability of at least 70% for a 75-hour operating period.

#### 1.3 Results

Table I summarizes the individual results for each day as well as the cumulative availability and test hours. After the third day, the system showed an increase in availability reaching a peak of 95.2% on the final day. A total of 103.3 hours of accountable operating time (either uptime or downtime) was achieved over the test period. The 4th through 11th day of testings resulted in 80.7 hours of operating time and an average accumulated availability of 82.6%. A copy of the System Event Log for the total test period is attached to this report as Appendix A. The clock frequency measurements are presented in Section 6. These results verify that the system operated at an average clock frequency of 15.75 MHz and at no time was operating at or below 15.0 MHz. These results exceed both

the minimum requirement of 70% availability for 75 hours and the minimum clock rate of 15.0 MHz. and are submitted herein as evidence of compliance with these objectives.

DATE	DAY	UPTIME UT(min)	TOTAL UPTIME E UT (min)	DOWNTIME DT (min)	OPERATING TIME OT (min) (UT+DT)	TOTAL OT (min)	DAILY AVAILABILITY (A%)	CUMULATIVE AVAILABILITY (A% CUM)	CUMULATIVE TIME (Hours)
11/27	1	348	348	241	589	58 <b>9</b>	59.1%	59.1	9.8
11/28	2	157.5	505.5	295.5	453	1042	34.7	38.9	17.4
11/29	3 ·	111	616.5	206	. 317	1359	35.0	38.0	22.6
11/30	• 4	321	937.5	170	491	1850	65.4	45.3	30.8
12/1	5	502	1439.5	203	<b>7</b> 05	2555	71.2	44.6	42.6
12/2	6	628	2067.5	115	743	<b>32</b> 98	84.5	59.6	54.9
12/4	7	582	2649.5	80 _	662	3960	87.9	64.4	66.0
12/5	8	569	3218.5	70	639	4599 ·	89.0	67.8	76.7
12/6	9	592	3810.5	103	695	5294	85.2	70.1	88.2
12/7	10	549	4359.5	86	635	5929	86.5	71.8	98.8
12/8	· 11	256	4615.5	13	269	6198	95.2	72.8	103.3
				SUMM	ARY OF LAST	80.7 HOUR	S		
11/30 to 12/8	4-11		<b>3</b> 999			4839		82.6	80.7

# 1.4 CONCLUSIONS

An examination of the test results permits the following general conclusion:

During a simulated operating situation, the ILLIAC IV hardware exhibited an MTBF\* from "hard" permanent type failures of 3.1 hours and an MTTR\*\* for these hard failures of .5 hours. Using this data as a base, an availability of 86% can be calculated. The difference between this figure and the 82% figure reported above lies primarily in the addition of down time penalties resulting from transient errors.

- \* MTBF Mean Time Between Failures, determined by dividing

  a given period of up time by the number of failures

  occurring in this time.
- \*\* MTTR Mean Time To Repair, determined by dividing a given
  amount of down time by the corresponding number of
  failures that caused that down time.

# 2. SUMMARY OF SYSTEM MALFUNCTIONS

Table II is a summary of system malfunctions occurring during the operating test period and contributing to the system down time. This summary encompasses the period of 30 November through completion of the test on 8 December 1972. It lists by date the event and failure tag of each malfunction, the test(s) failed, the corrective action and the resulting down time.

Table III (CAUSES OF FAILURES) lists by failure tag number any subsequent repair action and the probable cause of the failure. Of the 14 failures listed, there are 4 resulting from failed integrated circuits\*: 1 from a failed transistor, 1 from a faulty delay line, 1 from clock adjustment, 3 relating to connections (one of which was a human error) and 4 for which no apparent cause could be identified. Except for the unidentified failures, the causes approximate what was expected.

\*For the integrated circuits this would indicate a failure rate of .2 per million hours during the 80-hour operating period. Tust prior to beginning the test, the integrated circuit failure rate for the system was, on a weekly basis, ranging between .1 to .4 failures per million hours.

.

Date	Daily	Failure	Where Failure	Symptom(s)	· Corrective Action	System	Comments
	Event Log Item No.	Tag No.	Occurred	Test Failed	(Cause of Failure)	Down Time (Min.)	
11/30/7	2 105		PU 74 & 36	IDIAP	**	1 (T)	(T) = Transient mal- function; not isolated. Downtime based on a penalty.
	106		PU 7, 69 & 25	PE-PEM		9 (T)	
	112		PU 35 <sub>8</sub> ,41 <sub>8</sub> ,44 <sub>8</sub>	IDIAP		2 (T)	
	118		DISK	IDIAP		1 (T)	
<b>.</b>	136	42416	PU S/N 72	AIDS NORM	Rp1 S/N 72 ₩/64	125 (H)	(H) = Hard failure. Down Time includes
	137	42418	PU MEM	OPAL-MEM PROB	Rp1 S/N 47 w,'60	29 (H)	isolation and repair
	143-144		DISK	IDIAP	Recycle Sub Test	3 (T)	of malfunction.
12/1/7	161	42421	PU S/N 59	IDIAP	Rp1 S/N 59 w/74	86 (H)	
	167		DISK System	I/O PATH	One Disk Sys. Off-line	12 (H)	
	168		DISK System	I/O Path	One Disk Sys. Off-line	1 (H)	
	*110		DISK System	CU ROM	One Disk Sys. Off-line	3 (T)	25% Penalties Included for one DISK System
	113		DISK System	IDIAP	One Disk Sys. Off-line	1 (T)	being down.
	115		DISK/CU	IDIAP	Intermittent Delay Line	6 <b>(</b> H)	
	117-123	42422	DISK	PE-PEM	On DISK System	63 (H) _	
	130	42428	PU MEM	I/O PATH	Rp1 S/N 47 w/37	10 (H)	
	147		PUC 3	PE-PEM	Reseat PUC IRM Card	2 (H)	
į	152	42430	PUC 3 PU/#60	IDIAP	Rp1 S/N 60 w/36	17 (H)	
	153		DISK	IDIAP		2 (T)	
Separation of the section of the sec		n sequence followed	numbering of ev	ents,			
SELVIN TOURS TO SELVIN THE SELVIN	of test		proper function	ted, the recycle ing of the hard-			·
ryream a till						·	
I		ř	·		<b>!</b>	<u>.</u>	ı

TUDES IT DOUBLEST OF DIDINITING CHOICE

		Tradition 1	Where Failure	Symptom(s)	· Corrective Action	System	Comments
Date	Daily Event Log Item No.	Failure Tag No.	Occurred	Test Failed	(Cause of Failure)	Down Time (Min.)	
12/2/72	171		PU S/N 25	IDIAP (HIIDR)	Rpl RC504 Card	1 (T)	
12/2/12	174		PU S/N 25	IDIAP (HIIDR)	Rp1 DVR03 Card	105 (H)	Debugged on Pu Extenders
	_		s/n 24	IDIAP (HIIDR)	KPI DVKOS Cald		(by card swapping.
	203		PU 57 <sub>8</sub>	IDIAP (HAPE)		1 (T)	
	210		PUS/N8	PE-PEM (DVN)		2 (T)	
	_		PU S/N 59	PE-PEM (MUTPC)	·	J I	
	216		PU S/N 24	PE-PEM (1 error)		1 (T)	
	222	٠	CU	CU-ROM		5 (T)	
12/4/72	231	42977	CU/PU S/N 32	IDIAP	Rp1 S/N 32 w/30	56 (H)	Prime power loss. B6700, I/O & Quad down. Came up w/B6700 MEM,CU,PU,S/N 32, & I/O problems.
to the state of th	233	42978	DISK Controller	IDIAP	Rpl Transistor	4 (H)	Possibly a result of power loss.
	247		PU S/N 74	IDIAP	•	1 (T)	
	249		PU S/N 74	PE-PEM	Declared Spare	0 (T)	
	-		PU S/N 62	PE-PEM(ADEX)		1 (T)	
	254		PU (23 <sub>8</sub> )	IDIAP		1 (T)	
	264		PU S/N 74	PE-PEM (NORM)		1 (T)	
	266		PU S/N 62	PE-PEM(ADEX)	·	2 (T)	
	268		PU S/N 71	PE-PEM(ILE IME)	·	2 (T)	
1	278 ·		PU S/N 62	PE-PEM (ADEX)	Declared Spare	. 0	
	<u>-</u>		PU S/N <b>7</b> 4	PE-PEM(NORM etc	Declared Spare	0	
	-		PU S/N 8	PE-PEM(RAB,SAB)		2 (T)	
	298		PU S/N 59	PE-PEM(MLTPL)			
	-	·	PU S/N 60	PE-PEM(ADEX)		5 (T)	
1	- -		PU S/N 71	PE-PEM(ILE IME)		+	
		,					
	·			•			

Date	Daily !	Failure	Where Failure	Symptom(s)	· Corrective Action	System Down Time	Comments
	Event Log	Tag No.	Occurred	Test Failed	(Cause of Failure)	(Min.)	
	Item No.		0/Y (0	PE-PEM (ADEX)		2 (T)	
12/4/72 (Cont'd)	.; 1		PU S/N 60	1		2 (T)	
(COIL a)	300		PU S/N 71	PE-PEM (IME)		1 (T)	
	318		PU S/N 59	IDIAP (HAPE)	•	3 (T)	
12/5/72	331		ROM (CU)	IDIAP (HACPM)		h .	
	332		PU S/N 59	IDIAP (HAPE)		) 3 (T)	
	-		S/N 20	IDIAP (HAPE)		1 (7)	
	339		PU S/N 59	PE-PEM (MULTPL)		1 (T)	Problem cleared up under
	343		PU S/N 47	PE-PEM (MEM 1&2)	Recycle Sub Tests (H)	4 (H)	recycle, see event 347.
	-		s/n 59	PE-PEM (MULTPL)		1 (T)	PU S/N 47 tested in PEMX
	347	42988	PU S/N 47	PE-PEM(MEM 1&2)	Rp1 S/N 47 w/71 (H)	26 (H)	
	357	42986	PU S/N 71	PE-PEM(ILE, IME,	Rpl during PM period	No DT	Designated as spare per ground rules.
CO			s/N 24	PE-PEM (MULTPL)		1 (T)	·
			s/n 59	PE-PEM(MULTPL)			
	370	-	-	-	. <del>-</del>	23	No spare PU's.Could not come up after PM. (DT=23)
	0.77		PU S/N 71	PE-PEM(ILE IME)	-	1 (T)	Designated Spare.
	377		•	IDIAP (HIIDR)		1 (77)	
	379		SU 03	IDIAF (HILDR)	Parity Error Recycle Sub Test	1 (T)	Designated Spare
	383		PU S/N 71	PE-PEM(ILE IME)	•		Designated Spare.
	·		S/N 59	PE-PEM (MULTPL)		4 (T)	
		42999	S/N 25	PE-PEM (MULTPL)		¥.	
	290		PU S/N 59	PE-PEM (MULTPL)		2 (T)	
			and the state of t				
•		•	¥g.	·			
Į			1	`-		1	

•				•	•	. •	·
Date	Daily Event Log Item No.	Failure Tag No.	Where Failure Occurred	Symptom(s) Test Failed	Corrective Action (Cause of Failure)	System Down Time (Min.)	Comments
12/6/72	299	*	PU S/N 17	IDIAP (HAPE)	Rp1 PU 17 w/71 (H)	63 (H)	
	_	42998	PU S/N 40	IDIAP (HAPE)	Rp1 card RSG13 (H)		,
	309	,,	Unknown	IDIAP (HACPM)		3 (T)	
1	313		PU S/N 71	·	Recycle Sub Tests (H)	5 (H)	Declared Spare.
-	-		PU S/N 55	PE-PEM (SHABR)		0 (T)	Less than 30 sec. on initial run.
	320 321		CU CU	CU-ROM CU-ROM		1 (T) 1 (T)	
	350		PU S/N 71	PE-PEM (ILM, IME)	•		Declared Spare.
	· -		s/n 60	PE-PEM (MULT 8)		> 4 (T)	
	_		s/n 24	PE-PEM (ADEX)		U	
	352		Unknown	IDIAP (MEMORY)	·	3 (T)	
-3	371		PU S/N 10	PE-PEM (MANY)	Recycle Sub Tests (H)	19 (H)	No errors found on recycl
	-		PU S/N 71	PE-PEM (IB)		2 (T)	of tests.
	373		PU S/N 10 (PUC)	PE-PEM (MANY)	Reseat PUC/PE (H) Paddle Board	3 (H)	
	381		PU (14 <sub>8</sub> )	IDIAP (HAPE)		1 (T)	
A							
	,		* See event 39	3 Failure Tag 4228	1 below.		
•							

TUDES II SOLEREI OL SISIELI LIEUTONSIZONS

<u> </u>	Daily !	Failure	Where Failure	Symptom(s)	· Corrective Action	Sys		Comments
Date	Event Log	Tag No.	Occurred	Test Failed	(Cause of Failure)	L.	Time	•
	Item No.					(Mi		
12/7/72	<b>3</b> 89	42279	PUC 6	IDIAP (HACPM)	Clean & swap cub logic boards in PUC 6 (H)	9	(H)	
	390 391		PU S/N 8 PU S/N 22	IDIAP (HAPE) IDIAP (HAPE)	Rp1 S/N 8 w/S/N 22 Rp1 card in PU	12 13	(H)	
	393	42281	PU S/N 17	IDIAP (HAPE)	Rpl I.C.	.0		Occurred during other repair (391 above)
. •	402		PU S/N 59	PE-PEM (MULTPL)		-		20pu22 (00 a a )
	_		s/n <b>7</b> 5	PE-PEM(NAND)	·			
	<b>-</b>	,	S/N 52	PE-PEM (NAND)				
	· <b>-</b>		s/n 63	PE-PEM (NAND)				
	-		S/N 12	PE-PEM (NAND)				•
	-		s/n 43	PE-PEM (NAND)	,	0	(T)	No transient penalty required. Single non-
	-		s/n 41	PE-PEM(NAND)				repeated error; probabl
	-		s/n 50	PE-PEM (NAND)		<u>k</u>		CU bug.
	-		S/N 25	PE-PEM (NAND)		3	(T)	·
	-		s/n 65	PE-PEM (MULTPL)		V		
	407		Apparent Soft- ware	(HACIA)		2	(T)	
	408		PU S/N 59	PE-PEM (MULTPL)		1	(T)	<b>3</b>
	410		PU S/N 59	PE-PEM (MULTPL)		3	(T)	3 Recycles of Sub Test
	414		CU	(HACIA)	Design Fix on CU (H)	í	` '	1
	426		PU S/N 55	IDIAP(HAPE)	Board	3	<b>(</b> T)	į į
	430		PU S/N 55	IDIAP(HAPE)		. 1	(T)	Recycle 4 times. Passed 3 times.
	431		PU S/N 55	IDIAP(HAPE)		8	(T)	Recycle 4 times. Passed 3 times.
	432		PU S/N 55	IDIAP(HAPE)		1	<b>(</b> T)	Recycle 4 times. Passed 3 times.
•	436		PU S/N 59	PE-PEM(MULTPL)	No Recycleonly 1 error. LEADER PU FAILS NANDRecycled tests.	} 2	<b>(</b> T)	

Date	Daily Event Log Item No.	Failure Tag No.	Where Failure Occurred	Symptom(s) Test Failed	·Corrective Action (Cause of Failure)	System Down Time (Min.)	Comments
12/7/72	*440 *443		Unknown Unknown	IDIAP(HICQ) IDIAP(HAPE)	Recycle failed. Possible software pblm. Recycle HIIDR.	2 (T) 3 (T)	
	+444		SU 02	IDIAP(HICQ HAPE)	Took Su 02 off line passed HICQ, fails result descriptor. Cleared I/O-reran OK.	5 (H)	
	<sup>+</sup> 420		PU S/N 72	IDIAP (ROUTE)	Rp1 S/N 72 w/SN 24	15 (H)	Technician interpreted printout improperly. Called in another tech. who solved pblm in 15 mi
And the second s	429		1/0	IDIAP(HACIA)	Recycle Sub Test 4 times - Intermittent between I/O & Quad.	9 (T)	
e. garanaga anakagana	440		PU S/N 41	PE-PEM (MULTPL)	Designated Spare	1 (T)	
				ata to determine t	he problem area. gain, went from 444 to		
And Designation of Principles		4. A.S. A.C. A.C. A.C. A.C. A.C. A.C. A.C					
The way and the state of the st		S. YAR. A STEER ST. VIII.					
		for Barabas. Bernandis.					

TABLE III

CAUSES OF FAILURES

FAILURE TAG	FAILURE	ACTION	CAUSE
42416	PU S/N 72 failed Ames Norm Test	Debug in Quad. Failure disappeared	Unknown
42418	PU S/N 47 failed Memory Test	Test on PEMX 1.5 hrs. Did not reoccur	Unknown
42421	No response to IDIAP	Debug in Quad. Plug in connectors	PE to MLU Paddle boards not connected
42422	PE-PEM TEST	Trace failure in Quad. Adjust delay line.	Intermittent delay line
42428	PU S/N 47 failed MEM test	Test on PEMX and PEX. No failure isolated	Unknown
42430	PUC 3, PU S/N 60 Failed IDIAP	Debug in Quad.	Adjusted clocks
42977	PU S/N 32 failed IDIAP	Test on PEX. Replaced I.C.	Internal short in Integrated Circuit
42978	Unable to load queuer after power fault due to bad clocks	Trace failure in Disk Controller 	Failed transistor
42988	PU S/N 47 failed AIDS MEM test	Test on PEMX Clean and tighten connection	Poor contact on voltage bus
42986	PU S/N 71 failed AIDS test	Test on PEX O.K. on test	Unknown
42999	PU S/N 25 failed MULT8 test	Test on PEX Replace I.C.	Internal short in Integrated Circuit

TABLE III (Cont'd)

FAILURE TAG	FAILURE	ACTION	. CAUSE
42998	PU S/N 40 failed route	Test on PEX Replaced Card	Internal short in Integrated Circuit
42279	PUC 6 failed IDIAP test	Debug on-line Clean and swap logic boards	Apparently poor contacts
42281	PU S/N 17 failed OPAL test MFIND	Test on PEX Replaced I.C.	Failed Integrated Circuit. (one pin stuck low)

#### 3. AVAILABILITY CALCULATION

In accordance with the acceptance test procedure, system availability is determined by the following rule:

"Availability (A) is defined as uptime (Tu) divided by the sum of uptime (Tu) and downtime (Td)"

$$A = \frac{Tu}{Tu + Td}$$

The test requirement was for an availability of 70% or better for a minimum of 75 hours of system operating time (uptime plus downtime).

The period selected for the availability calculation was from 30 November to 8 December, encompassing 66 hours and 39 minutes of uptime, and 14 hours of downtime, with a total operating time of 80 hours and 39 minutes.

Therefore: 
$$A = \frac{66 \text{ hr.} 39 \text{min.}}{66 \text{hr.} 39 \text{min.} + 14 \text{hr.}} = 82.6\%$$

# 4. MTBF AND MTTR FOR SYSTEMS COMPONENTS

Table IV lists by system components, the number of "hard" failures, the corresponding downtime, and the resulting MTBF and MTTR. In several cases, no fault was isolated and the resulting MTTR includes the time spent in attempting to isolate the non-recurring fault.

In addition to the "hard" failures, there were 53 cases in which more than one test error occurred but was not repeated on subsequent tests. These failures were considered to be "transient" failures. An additional downtime of 1 hour and 21 minutes was added as a penalty for these failures as specified in the Acceptance Test procedure for ILLIAC IV Computer System, Burroughs Document No. IL4-TP14/15 Rev. A dated 15 November 1972.

MTBF and MTTR for System Components

TABLE IV

COMPONENT	FAILURES	DOWNTIME	MTBF	MTTR
Processing Units	15	420 min	4.9 hrs	.47 hrs
Control Unit	2	9 min	40.2 hrs	.08 hrs
Control Unit Power Supplies	0	0		
Processing Unit Cabinets Logic Power Supplies Cables & Connections	3 0 1	27 min 0 2 min	26.8 hrs  80.6 hrs	.15 hrs  .03 hrs
I/O Subsystem	1	9 min	80.6 hrs	.15 hrs
Parallel Disk System  Disks  Disk File Controller  Electronic Unit	1 1 1	5 min 4 min 63 min	80.6 hrs 80.6 hrs 79.7 hrs	.08 hrs .07 hrs 1.05 hrs

# 5. SUMMARY OF B6700 MALFUNCTIONS

Approximately 2 hours of non-productive time during the acceptance test was charged against the B6700. Table V lists the B6700 malfunctions that occurred during the test.

TABLE V

LIST OF MALFUNCTIONS AND RESULTING NON-PRODUCTIVE TIME

Date	Event		Non-Productive Time
11-27-72	1. One B6700 Memo	ory Off-line	
	2. Memory Parity	Error	2 min.
11-28-72	1. B6700 Down; re No halt load r		3 min.
	2. B6700 Down; ha	alt loaded 4 times	20 min.
11-29-72	1. B6700 Memory;	CM 1/N down	7 min.
	2. B6700 Down; me	emory parity error	15 min.
11-30-72		th directory damage in starting test	33 min.
12-2-72	1. Memory parity	error	5 min.
12-4-72		cop caused B6700 to memory during transie off also.	nt
	2. B6700 halt loa	ad	4 min.
12-5-72	1. B6700 halt loa	ad	15 min.
	2. B6700 halt loa	ad.	9 min.
12-6-72	1. B6700 halt loa	ad "	3 min.
	2. B6700 halt loa	ad	4 min.
12-8-72	1. B6700 halt loa Lost part of t		14 min.
	2. B6700 halt loa	ad	3 min.

# 6. QUADRANT CLOCK FREQUENCY

The Quadrant clock frequency was measured daily prior to the beginning of the test period. The measurement was accomplished using a Tektronic Model 454 oscilloscope.

The scope was calibrated against a Tektronix constant amplitude signal generator type 190A, with an accuracy of 2 percent. The scope measurements were within .8 percent of the generator setting, hence the accuracy of the daily clock period measurement is approximately ± 2.8 percent (both equipments used were within their current calibration periods).

The daily measurements (recorded on the daily check list) were as follows:

Date	Clock Period	Frequency (MHz)
11-27	63.5 n sec	15.75 <u>+</u> .44
11-28	63.5	15.75 ± .44
11-29	63.8	15.67 <u>+</u> .44
11-30	63.8	15.67 <u>+</u> .44
12-1	63.0	$15.87 \pm .44$
12-2	63.0	$15.87 \pm .44$
12-4	63.5	$15.75 \pm .44$
12-5	63.5	$15.75 \pm .44$
12-6	63.5	$15.75 \pm .44$
12-7	63.5	15.75 <u>+</u> .44
12-8	63.5	$15.75 \pm .44$

The above data substantiates that the Quadrant clock operated at frequency greater than 15 MHz at all times (the lowest probable level being 15.23 MHz and the highest 16.31 MHz). The nominal operating level for the test period is approximately 15.75 MHz.

#### 7. ENVIRONMENTAL CONDITIONS

A record of readings for the environmental conditions is included in the Daily Check List. The list includes the Quadrant and room temperature and humidity as well as the line voltage readings.

In general, the environment was such that it had no deleterious affect on the system operation and performance, with the exception of power drops on 3 and 4 December which resulted in 2 hours 24 minutes of non-productive time during the prime shift on 4 December and hampering maintenance and corrective action efforts on the evening of 3 December and early morning of 4 December. The Quadrant line voltages remained within the test specification of 208 vac  $\pm$  10%, with lowest reading being 205.7 vac ( $\emptyset$ A-B), and the highest reading being 210.9 vac ( $\emptyset$ B-C).

The room temperature remained within the specified level of 65°F to 80°F throughout the test. However, the room humidity remained below the specified level (40% R.H. to 60% R.H.) in the range from 36% to 37% for most of the test except on 3 December when there was a rise to 64%. This latter condition was immediately corrected. The condition of the low humidity is not considered to have caused any problems.

Low humidity also occurred in the Quadrant going down to 39% R.H. This is not considered to have been any problem as the specified levels were 45% to 55% R.H., with a recommended change of 40% to 55% R.H. in order to provide a lower nominal humidity.

Quadrant temperature specified to be held within 68°F to 72°F, fell to 65°F on the morning of 5 December. This occurred during the scheduled maintenance period and caused no known delays.

Recording charts for the room and Quadrant temperature and humidity are on file with the NASA/Ames Operations Office. Charts for an auxillary temperature and humidity recorder operated in the room near the Quadrant are attached to the original copies of the System Event Logs.

TABLE VI
PRODUCT ASSURANCE
DAILY CHECK LIST

TIME	QUAD TEMP	QUAD	ROOM	ROOM	QUAD	QUAD	LINE	VOLT	1 U.A.	
	o <sub>F</sub>	HUMID %	${\overset{\mathtt{TEMP}}{\circ}_{F}}$	HUMID %	, .	ØA-B	ØB-C	ØC-A	Q.A. INIT	REMARKS
0646	68	45	60	50	15.7MHZ 63.5NS	207	207	207	F.D.	
0640	66	40	68 <sup>0</sup>	38%	15.7MHZ 63.5NS	205.7	205.6	209.4	F.D.	Temp in Quad below test spec. 68-72
0635	66	44	70 <sup>o</sup>	38%	63.8NS	207.7	206.0	209.7	S.K.	Humid in roo below spec. 40%-60%
0640	680	40	70°	36%	63.8NS	205.7	209.0	207.2	F.D.	"
0642	68 <sup>0</sup>	42	70°	<b>3</b> 8%	63.0NS	207.4	208.0	207.0	R.A.S.	
0645	68	42	69 <sup>0</sup>	39%	63.0NS	207.4	210.4	208.9	R.A.S.	
0640	68	44	69	39	63.5NS	206.4	209.5	207.7	R.A.S.	
0645	65	42	69	36	63.5NS	206.0	208.9	209.3	R.A.S.	
0705	68	44	70	38	63.5NS	206.9	210.0	208.3	R.A.S	
0650	69	43	69	37	63.5NS	207.8	210.9	209.2	R.A.S.	
0720	69	42	68	38	63.5NS	206.7	209.7	208.0	R.A.S	
	0640 0635 0640 0642 0645 0645 0705	0640       66         0635       66         0640       68°         0642       68°         0645       68         0645       65         0705       68         0650       69	0640       66       40         0635       66       44         0640       68°       40         0642       68°       42         0645       68       42         0640       68       44         0645       65       42         0705       68       44         0650       69       43	0640       66       40       68°         0635       66       44       70°         0640       68°       40       70°         0642       68°       42       70°         0645       68       42       69°         0640       68       44       69         0645       65       42       69         0705       68       44       70         0650       69       43       69	0640       66       40       68°       38%         0635       66       44       70°       38%         0640       68°       40       70°       36%         0642       68°       42       70°       38%         0645       68       42       69°       39%         0640       68       44       69       39         0645       65       42       69       36         0705       68       44       70       38         0650       69       43       69       37	0640       66       40       68°       38%       15.7MHZ 63.5NS         0635       66       44       70°       38%       63.8NS         0640       68°       40       70°       36%       63.8NS         0642       68°       42       70°       38%       63.0NS         0645       68       42       69°       39%       63.0NS         0640       68       44       69       39       63.5NS         0645       65       42       69       36       63.5NS         0705       68       44       70       38       63.5NS         0650       69       43       69       37       63.5NS	0640       66       40       68°       38%       15.7MHZ 63.5NS       205.7         0635       66       44       70°       38%       63.8NS       207.7         0640       68°       40       70°       36%       63.8NS       205.7         0642       68°       42       70°       38%       63.0NS       207.4         0645       68       42       69°       39%       63.0NS       207.4         0640       68       44       69       39       63.5NS       206.4         0645       65       42       69       36       63.5NS       206.0         0705       68       44       70       38       63.5NS       206.9         0650       69       43       69       37       63.5NS       207.8	0640       66       40       68°       38%       15.7MHZ (63.5NS)       205.7       205.6         0635       66       44       70°       38%       63.8NS       207.7       206.0         0640       68°       40       70°       36%       63.8NS       205.7       209.0         0642       68°       42       70°       38%       63.0NS       207.4       208.0         0645       68       42       69°       39%       63.0NS       207.4       210.4         0640       68       44       69       39       63.5NS       206.4       209.5         0645       65       42       69       36       63.5NS       206.0       208.9         0705       68       44       70       38       63.5NS       206.9       210.0         0650       69       43       69       37       63.5NS       207.8       210.9	0640       66       40       68°       38%       15.7MHZ (63.5NS)       205.7       205.6       209.4         0635       66       44       70°       38% (63.8NS)       207.7       206.0       209.7         0640       68°       40       70°       36% (63.8NS)       205.7       209.0       207.2         0642       68°       42       70°       38% (63.0NS)       207.4       208.0       207.0         0645       68       42       69°       39% (63.0NS)       207.4       210.4       208.9         0640       68       44       69       39 (63.5NS)       206.4       209.5       207.7         0645       65       42       69       36 (63.5NS)       206.0       208.9       209.3         0705       68       44       70       38 (63.5NS)       206.9       210.0       208.3         0650       69       43       69       37 (63.5NS)       207.8       210.9       209.2	0640       66       40       68°       38%       15.7MHZ 63.5NS       205.7       205.6       209.4       F.D.         0635       66       44       70°       38%       63.8NS       207.7       206.0       209.7       S.K.         0640       68°       40       70°       36%       63.8NS       205.7       209.0       207.2       F.D.         0642       68°       42       70°       38%       63.0NS       207.4       208.0       207.0       R.A.S.         0645       68       42       69°       39%       63.0NS       207.4       210.4       208.9       R.A.S.         0640       68       44       69       39       63.5NS       206.4       209.5       207.7       R.A.S.         0645       65       42       69       36       63.5NS       206.0       208.9       209.3       R.A.S.         0705       68       44       70       38       63.5NS       206.9       210.0       208.3       R.A.S.         0650       69       43       69       37       63.5NS       207.8       210.9       209.2       R.A.S.

# APPENDIX

#### SYSTEM EVENT LOG

# GENERAL

The attached System Event Log provides a history of each operation or event in sequence by item number; with the time of occurrence, the corresponding UP, DOWN or NON-PRODUCTIVE time. It was maintained by Burroughs Quality Assurance representatives and each event is initialed by the Q.A. representative in attendance at that time.

A carbon copy of the original of this log was provided to NASA/Ames upon completion of the test.

#### Determination of UP, DOWN, and NON-PRODUCTIVE Time

Variances to the Acceptance Test Procedure in determination of up,

down and non-productive time were agreed upon by Burroughs and NASA/Ames

Representatives subsequent to the initiation of the test. Application of the variances were made where circumstances produced situations anticipated by the variances.

- 1. Equipment which is being maintained at the beginning of the test will not contribute to <u>down</u> time until maintenance has been satisfactorily completed.
- 2. Transient failures are non-repeatable and non-verifiable errors.

  Transient down times penalties varied from 10% to 50% of the duration of the subtest during which the non-repeatable error occurred.
- 3. Hard failures were defined as more than one error on a single test or one or more errors occurring on the same hardware on a repeated test. In this case, the following procedure is implemented: cycle failing test for two(2) minutes in error print option -- a) if NO errors occur in the two(2)-minute cycle, then test is complete. Down time penalty in this case is equal to the initial subtest time. The two(2)-minute cycle is considered up time, b) if ERRORS occur during the two(2)-minute cycle, then the test must be stopped and the failure must be fixed by on-line repair or spares substitution. Down time penalty is for initial subtest time plus the two(2)-minute cycle, plus any additional cycles, plus on-line repair or replacement time, plus all verification time.
- 4. No penalty was issued for a single error in the ROM test if the test was cycled twice without further error.

5. Inasmuch as the full complement of debugged spare PUs was not available at the start of the test, it was determined that up to eight PUs could fail without resultant down time. During this test the situation never arose which required invoking this no penalty provision for more than two PUs. It should be further noted that in the last half of the 80 operating hours, there were always 64 PUs operating.