

SMT

SOLDERING

**IT'S
EASIER THAN
YOU THINK!**



BY:

GREG PEEK (SMT GURU)
SILICONFARMER@SILICONFARMERS.COM

DAVE ROBERTS (ART & LAYOUT)
SWSODBUSTER@SILICONFARMERS.COM

FEEL FREE TO DOWNLOAD & DISTRIBUTE
THIS TO ALL YOUR FRIENDS!

WWW.SILICONFARMERS.COM/SMTMANGA





DISTRIBUTE WIDELY!

ELECTRONIC TECHNOLOGY IS CHANGING ... (AND FAST!)

S.M.T. Abbreviations & Acronyms


SMT is the three letter acronym for surface mount technology.

MOST PARTS ARE NOW AVAILABLE IN SURFACE MOUNT VERSIONS



AND MANY PARTS ARE ONLY AVAILABLE IN SMT

HAHA!




HELP! I'M SO ATTINY AND I CAN'T GET UP!



SMT TAKES LESS SPACE THAN THROUGH HOLE, SO WE GET COOLER, SMALLER STUFF...



SURFACE MOUNT USES PADS, NOT HOLES, TO MOUNT PARTS TO THE BOARD




**T
H
R
O
U
G
H
H
O
L
E**




**YES, SMT PARTS ARE SMALL!
SOME TIMES REALY REALY SMALL!!**

**YOU MIGHT THINK SMT CAN
ONLY BE DONE BY PROFESSIONALS
WITH EXPENSIVE EQUIPMENT
IN A BIG FACTORY...**



**BUT WE ARE GOING TO
SHOW YOU HOW TO DO IT
INEXPENSIVELY AT HOME**

**THE PARTS ARE SMALL, BUT WITH THE
RIGHT TOOLS SMT IS EASY TO SOLDER...**




**WITH PRACTICE, YOU MAY EVEN
FIND IT EASIER THAN THROUGH HOLE**

SOLDERING IRON


**AN INEXPENSIVE "PENCIL" IRON
CAN BE EASILY USED TO SOLDER SMT**

**BUT A TEMPERATURE CONTROLLED
IRON MAKES IT MUCH EASIER.**

**AN ANALOG TEMPERATURE CONTROL WORKS
JUST AS WELL AS A DIGITAL FOR LESS COST**



A GOOD SOLDERING TIP IS MORE IMPORTANT THAN AN EXPENSIVE IRON AND FAR CHEAPER!




**THE ROUND POINTED TIP THAT COMES WITH MOST IRONS ISN'T THE BEST FOR SMT
A FLAT TIP ABOUT AS WIDE AS THE PINS OR PARTS YOU ARE SOLDERING IS BEST**

- WE RECOMEND A 1 TO 2 MM "SCREWDRIVER" OR "CHISEL" TIP

SOLDER CHOICES ARE SIMILAR FOR SMT AND THROUGH HOLE.


THERE ARE SEVERAL TYPES, EACH WITH TRADE OFFS!



WE RECOMMEND FOR SMT

- LEADED 63/37 OR 60/40 EITHER IS FINE
- RMA FLUX
- THINNER IS BETTER (IE. $0.032'' = 0.8 \text{ mm}$)

**TWEEZERS ARE A MUST-HAVE TOOL FOR SMT
LIKE DIAGONAL CUTTERS FOR THROUGH HOLE,
A GOOD PAIR OF TWEEZERS WILL REALLY MAKE
THE JOB EASIER**




**SMT PARTS ARE SO SMALL THAT A VERY SMALL
MAGNETIC OR STATIC CHARGE CAN MAKE
PARTS CLING TO THE TWEEZERS.**

REMEMBER TO FOLLOW THESE TIPS:


- ⚡ ELECTRIC SUPPLIERS SELL ANTI-MAGNETIC, ANTI-STATIC TWEEZERS FOR UNDER \$5**
- ⚡ IT'S EASY TO BEND THE FINE TIPS MAKING THEM USELESS.
SO DON'T USE THEM TO PRY OR FORCE ANYTHING**
- ⚡ FLUX RESIDUE COLLECTS ON THE TIPS SO CLEAN THEM WITH ALCOHOL OCCASIONALLY**
- ⚡ AND AVOID MAGNETS!!!**

**TO WORK WITH THE SMALL PARTS YOU WILL NEED MAGNIFICATION
AND GOOD MAGNIFICATION MAKES "EVERYTHING" EASIER!**


POSSIBLE MAGNIFICATION CHOICES INCLUDE:



**HEAD MOUNTED MAGNIFIER
CHEAP, BUT TAKES SOME
GETTING USED TO IT!**



**MAGNIFYING RING LAMP
IT'S BETTER AND COSTS
MORE BUT WORTH THE EXTRA COST**




**STEREO ZOOM
MICROSCOPE
THE VERY BEST, BUT
ALSO VERY EXPENSIVE!**

TIP: A 10X JEWELERS LOUPE IS CHEAP AND VERY HANDY FOR INSPECTING THE SOLDER JOINT CLOSE UP




**MYSTERIOUS EFFECT!
THE GREATER THE
MAGNIFICATION
THE STEADIER YOUR
HAND BECOMES**

**SOME OTHER BITS YOU
WILL NEED!
BRASS TIP CLEANER
OR SPONGE:**




SOLDER BRAID:

**FOR REMOVING SOLDER,
YOUR OLD "SOLDER SUCKER"
WON'T WORK FOR SMT**




ISOPROPYL ALCOHOL & BRISTLE BRUSH:

FOR CLEANING EXCESS FLUX




SOLDER FLUX:

**A SMALL BOTTLE, PEN
OR SYRINGE**



WHAT YOU DON'T NEED!

- HOT AIR GUN
- GLUE
- PART HOLDING GIZMOS
 - LIKE A VISE OR HELPING HANDS
- MICROSCOPE
- THE STEADY HANDS OF A SURGEON :)




ENOUGH TALK!

LET'S GET TO WORK



REMEMBER:

**A CLEAN, TINNED TIP IS EVEN
MORE IMPORTANT FOR SMT...**




**THAN THROUGH HOLE
SOLDERING!**

HEAT UP YOUR SOLDERING IRON.


**ABOUT 310°C / 590°F IF YOU USE LEAD
SOLDER SUCH AS 63/37.**

**LEAD FREE SOLDER TAKES A HIGHER
TEMPERATURE AROUND 350°C / 662°F.**



LET'S START WITH A SIMPLE 2 PIN PART LIKE A RESISTOR OR A CAPACITOR.

THESE PARTS USUALLY COME ON TAPE CUT FROM A LARGER REEL OF PARTS.




USE YOUR SMT TWEEZERS TO CAREFULLY PULL BACK ENOUGH CLEAR TAPE TO RELEASE ONE PART

AND DROP THE PART ON WHITE PAPER SO YOU CAN SEE IT...

STEP 1: TIN

POSITION THE PCB UNDER YOUR MAGNIFIER & TIN ONE PAD WITH SOLDER...




THE PAD SHOULD BE COMPLETELY TINNED, BUT AVOID APPLYING EXCESS SOLDER. REMEMBER SMT DOES NOT NEED MUCH SOLDER.

TIP:


IF ONE PAD IS EASIER TO SOLDER, START WITH THE EASY PAD. WITH THE PART SOLDERED DOWN ON ONE PAD, THE SECOND PAD WILL BE EASIER TO DO...

STEP 2: POSITION

PICKUP THE PART ON BOTH SIDES WITH YOUR TWEEZERS & PLACE THE PART NEAR THE TINNED PAD.




BE PATIENT - THIS CAN BE THE HARDEST PART! DON'T GRIP YOUR PARTS TOO HARD, OR A CLICK IS THE LAST SOUND YOUR PART WILL MAKE BEFORE DISAPPEARING



STEP 3: SOLDER PIN 1


REHEAT THE TINNED PAD. WHEN THE SOLDER MELTS, SLIDE THE PART INTO POSITION WITH ONE END IN THE MOLTEN SOLDER.



PULL THE SOLDERING IRON AWAY, HOLD THE PART FOR A SECOND WHILE THE SOLDER COOLS AND BECOMES SOLID

STEP 4: SOLDER PIN 2

GRAB YOUR SOLDER AGAIN. NOW TOUCH THE TIP OF THE YOUR IRON TO THE SECOND PAD & TO THE END OF THE RESISTOR. NOW APPLY SOLDER TO MAKE THE JOINT...




TIP:

IF YOU HAVE TROUBLE TRY PUTTING LIQUID FLUX ON THE PAD AND THEN TRY AGAIN!

STEP 5: INSPECT

***PULL THE SOLDERING IRON AND SOLDER AWAY!
(REMEMBER TO ADMIRE YOUR WORK)***



THERE SHOULD BE NICE SMOOTH "TENTS" OF SOLDER AT EACH JOINT...

STEP 4: THE ALTERNATE METHOD

***ADD A LITTLE EXTRA SOLDER TO YOUR IRON TIP.
FLUX THE PAD.***


***NOW TOUCH THE IRON TO THE PAD AND THE
SOLDER SHOULD WICK ON THE PART FORMING
A NICE JOINT...***



***THIS TECHNIQUE IS EASIER, FASTER AND
WORKS WELL BUT IT DOES LEAVE A LOT
OF FLUX ON YOUR BOARD!***

STEP 5: INSPECT

***PULL THE SOLDERING IRON AND SOLDER AWAY!
(REMEMBER TO ADMIRE YOUR WORK)***




***THERE SHOULD BE NICE SMOOTH "TENTS"
OF SOLDER AT EACH JOINT...***


TIP: TO STEADY THE TIP OF YOUR IRON, REST YOUR WRISTS ON THE TABLE WHILE YOU WORK...

DON'T USE A VISE, IT WILL LIFT YOUR BOARD TOO HIGH AND YOU WILL NOT BE ABLE TO STEADY YOUR HANDS...

MAKE SURE YOU WORK ON A SKID FREE SURFACE OR YOU WILL JUST BE CHASING YOUR WORK AROUND THE DESK!




**REMEMBER FLUX IS YOUR FRIEND!
IT CLEANS OXIDATION THAT YOU CAN'T EVEN SEE AND HELPS WITH HEAT FLOW**




IF YOU GET A COLD SOLDER JOINT, JUST ADD A DROP OF FLUX AND REHEAT!

IF YOU GET TOO MUCH SOLDER ON A JOINT, USE SOLDER BRAID TO REMOVE THE EXCESS...




**TIP:
TRIM OFF YOUR BRAID AS IT GETS COATED WITH SOLDER...
DON'T BE CHEAP - IT ONLY MAKES A MESS.**

WASN'T THAT EASY? SO FAR SO GOOD!




**NOW LET'S SOLDER AN IC
(THAT'S SHORT FOR INTEGRATED CIRCUIT)**




STEP 1: FLUX

PUT FLUX ON ALL OF THE PADS...



STEP 2: TIN


TIN ONE PAD...



THE EASIEST WAY IS TO ADD A LITTLE EXTRA SOLDER TO YOUR IRONS TIP, THEN TOUCH JUST ONE PAD. THE SOLDER WILL THEN FLOW ONTO THAT PAD.

STEP 3: POSITION


***PICK UP THE IC WITH YOUR TWEEZERS,
POSITION IT CAREFULLY ALIGNING IT TO ALL
OF THE PADS...***



DON'T LET GO YET!

STEP 4: SOLDER ONE PIN


***TOUCH THE TINNED PAD WITH THE HOT
IRON. THE PART SHOULD SETTLE INTO
POSITION WHEN THE SOLDER MELTS...***



***HOLD THE PART IN PLACE UNTIL YOU
REMOVE THE SOLDERING IRON!***

STEP 5: ADD SOLDER


NOW ADD MORE SOLDER TO THE TIP OF YOUR IRON, THEN TOUCH THE TIP TO THE PIN AT THE FAR DIAGONAL CORNER OF YOUR PART...



DOUBLE CHECK THAT ALL OF THE PINS ARE ALIGNED TO THE PADS. AFTER THIS STEP, IT'S VERY HARD TO REALIGN THE PINS.

STEP 6: SOLDER

NOW TOUCH EACH PIN WITH THE SOLDERING IRON TIP...




THE SOLDER SHOULD EASILY WICK ONTO THE PAD AND PIN ON THE IC. IF NOT, IT MAY BE TIME TO ADD MORE SOLDER TO THE IRONS TIP...



TIPS:

**1) REMEMBER: "INSIDE OUT, SMALL TO TALL"
ALWAYS START IN THE MIDDLE OF THE BOARD
AND WORK TO THE OUTSIDE OF THE BOARD**

**2) ALSO - DON'T HOLD YOUR IRON ON A PAD TOO
LONG. THE LITTLE SMT PADS CAN LOSE THEIR
GRIP ON THE PC BOARD WHEN HEATED TOO
LONG!**



**3) YOU DON'T HAVE TO REMOVE THE FLUX WHEN
YOU ARE FINISHED SOLDERING. BUT IF YOU
WANT TO CLEAN UP YOUR BOARD, USE AN
OLD TOOTH BRUSH AND RUBBING ALCOHOL**



WASN'T THAT EASY?

**JUST BE PATIENT AND
WORK CAREFULLY AND YOU'LL
HAVE A LIFETIME OF SMT FUN!**



**GOOD JOB & CONGRATULATIONS
ON FINISHING YOUR FIRST SMT PROJECT**

**YOU CAN DOWNLOAD YOUR OWN COPY
OF THIS SMT TUTORIAL AT:**

WWW.SILICONFARMERS.COM/SMTMANGA

**FEEL FREE TO PASS IT ALONG TO ALL OF
YOUR FRIENDS!**



**WE WOULD LIKE TO THANK THESE
FOLKS FOR ALL OF THEIR HELP &
INSPIRATION:**

**JEFF KEYZER (MIGHTYOHM.COM)
MARCUS NOWOTNY
ADAM WOLF
MERT EASTMAN**

INSPIRED BY "SOLDERING IS EASY"

[HTTP://MIGHTYOHM.COM/SOLDERCOMIC](http://MIGHTYOHM.COM/SOLDERCOMIC)



DISTRIBUTE WIDELY!