



Apple X/Lisa PRIAM Interface Card			
2011-09-17	Sheet 1 of 2	Rev. A	JDM
Notes: 1. There are NO 4-way connections on this diagram 2. Leading slash indicates signal is active low 3. Send corrections to: bugs@SigmaSevenSystems.com 4. Use this drawing at your own risk			

Reverse Engineered from:
 200884-2 PEI 2570 000071

Part Numbers Skipped
 R4

Spare

74LS125	74LS02
74LS02	74LS02

