

PLX PCI 9050RDK Software

Technical Update
October 14,1997

A. Overview:

The scope of this document encompasses the PLX PCI 9050RDK Software.

B. PCI 9050RDK Software Errata:

(A) Windows 95 Release 2 (OSR2)

We have seen some instances where the enclosed PLX PCI 9050 Windows95 driver (PLXSDK.VXD) does not work with Windows 95 release 2 which is also known as OSR2.

Solution/Workaround:

1. Windows95 Release 2 is not supported. Customers are advised to use a third party software from a company called KRFTech. Their software along with manuals is shipped in the PLX PCI 9050RDK box. This is a device driver development tool kit. The same driver will work on both Windows 95 and Windows NT. KRFTech can be reached at <http://www.krfttech.com>.
2. The source code for the Windows95 driver is enclosed in the PLX PCI 9050RDK package and may be modified to support Windows95 Release 2.