



1.) Imprinting the mold



2.) Heating positive above glass-transition temperature



3.) Removing the mold, bake-out

