

IBM TotalStorage™ Network Attached Storage 200



Release Notes

Network Attached Storage 200

6/29/01

THE INFORMATION CONTAINED IN THIS DOCUMENT IS PROVIDED ON AN "AS IS" BASIS. In no event will IBM be liable for damages arising directly or indirectly from any use of the information contained in this document.

First Edition (June, 2001)

This edition applies to the IBM 5194 TotalStorage Network Attached Storage 200 (Models 200 and 225, product numbers 5194-200 and 5194-225, respectively).

Order publications through your IBM representative or the IBM branch office servicing your locality. Publications are not stocked at the address below.

IBM welcomes your comments. A form for reader's comments is provided at the back of this publication. If the form has been removed, you may address your comments to:

International Business Machines Corporation
Design & Information Development
Department CGF
PO Box 12195
Research Triangle Park, NC 27709-9990
U.S.A.

You can also submit comments on the Web at www.ibm.com/networking/support/feedback.nsf/docsoverall.

When you send information to IBM, you grant IBM a nonexclusive right to use or distribute the information in any way it believes appropriate without incurring any obligation to you.

© Copyright International Business Machines Corporation 2001. All rights reserved.

US Government Users Restricted Rights – Use, duplication or disclosure restricted by GSA ADP Schedule Contract with IBM Corp.

Release notes

This document contains the release notes for the Network Attached Storage 200 (NAS 200). Unless otherwise noted, Models 200 and 225 of the product are collectively referred to as the NAS 200.

Refer to www.storage.ibm.com/support/nas for possible updates to these release notes and for copies of the base documents.

Administration notes

This section contains information on administering the NAS 200.

Additional storage notes

The following section contains Model 225 information on adding and configuring additional storage for the NAS 200.

Configuration of Unit ID switch on the 5194-EXU (Model 225 only)

The Unit ID switch comes with a factory default of ID 0. Because each 5194-EXU is on a separate SCSI channel connected to the Model 225's SCSI RAID card, you can leave this Unit ID configuration as ID 0 for any attached 5194-EXU units.

AntiVirus protection

You can perform AntiVirus scanning of the NAS 200 storage from clients having the appropriate access permissions. Also, you can install Norton AntiVirus Version 7.1 or later on the NAS 200 engine using normal Windows 2000 software installation procedures.

Depending on configuration options, AntiVirus scanning may use substantial CPU or disk resources. Therefore, you should carefully select scanning options and scan schedule.

Director Support Program problem on Recovery CD code image

If you use the Recovery CD to restore the preloaded software image on your NAS 200, and if you are using the IBM Director (or Tivoli IT Director) Management Console on your network to manage the appliance, the appliance name may no longer appear in the list of systems and devices. (The appliance name should appear in the list as IBM5194-xxxxxxx, where xxxxxx is the serial number of the appliance, located in the lower right corner of the bezel on the front of the appliance.) If this occurs, you will need to download and install a patch for the IBM Director Support Program that is part of the preloaded software on the appliance.

Go to www.storage.ibm.com/support/nas, and then go to the Downloads section under 5194 TotalStorage NAS 200 (Model 200 or Model 225) to find the patch package titled **IBM Director Support Program patch**. Download and install the patch on your appliance as instructed by the documentation accompanying the package.



Part Number: 38P8075



Printed in the United States of America
on recycled paper containing 10%
recovered post-consumer fiber.

(1P) P/N: 38P8075

